

I. Assembly the short bars and long bars onto the Shell




3. Slide the shell assembly onto the base

4. Mounting process finished





2. Mount the base onto flat surface





MOUNT-BASE


























	ITEMS;			MATERIAL;		
hardware	MOUNT-BASE				Zinc	
resources				WE IGHT;		
	FINISH:				1.945	g
PROPRIETARY AND CONFIDENTIAL				PROJECTION	A ~	
THE INFORMATION CONTAINED					}	
IN THIS DRAWING IS THE SOLE PROPERTY OF HARDWARE RESOURCES INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PREMISSION OF HARDWARE RESOURCES INC. IS PROHIBITED.	OTHERWISE SPECIFIED:	UNITS:	DRAWN BY:		DATE:	
			Alan liu			
		SIZE:	APPROVED BY	;	DATE:	
		A4				
		SHEET:	RELEASE LEV	EL:	REVISION:	
	DO NOT SCALE DRAWING					

